- Site Report -

Date: June 8, 2009

IRD Sales Order: 11013

To: ESS

From: John Folkerts

State: Indiana

Project Name/Location: Plymouth - Highway 31

Service Date(s): June 3, 2009

Job Description: Semi-annual maintenance needs to be performed.

Work Completed:

Checked functionality of site.

Measured and recorded data for all sensors.

· Measured and recorded all system power levels.

· Watched vehicle records to check weights.

System working well.

Work Remaining: None.

Schedule Include Estimate to Complete (on-track, ahead, behind): N/A.

Parts Used: None.

Part Name	Part Number	Quantity Used

Pre-mature Equipment Failure: None.

Mileage / Travel Time: 360 miles. 7 hours travel + 2 hour onsite = 9 hours total.

Safety Concerns: No special concerns.

Issues Related to Sub-Contractors: N/A.

Other Notes: None.

Action Items: None.

Item	Action Required	Ownership
1.		
2.		

3.	
4.	